From: Michal Haynes [mhaynes@aqmd.gov]

Sent: 12/17/2019 4:00:35 AM

To: Matt Kaczmarek [mattkaczmarek@bowyerenvironmental.com]

CC: Castellana, Ben [castellana.ben@epa.gov]; Jason Aspell [JAspell@aqmd.gov]; Garrett Kakishita [gkakishita@aqmd.gov]; Brett Bowyer [brettbowyer@bowyerenvironmental.com]; Tobias, Rod

[Rod.Tobias@westonsolutions.com]; Danny Dolan [dannydolan@bowyerenvironmental.com]; Zachary Gilmer

[zachgilmer@gmail.com]

Subject: Re: Tarps not covering the VOC contaminated Area

```
Mr . Kaczmarek;
```

12/13/18-South Coast AQMD, Air Toxic and Waste Management Unit, was notified per R1166, Site Specific plan that a 1,000ppm VOCs was measured during Soil remediation activities. This exceedance requires the excavated Soil to be directly loaded into sealed bin or haul off site in sealed trailers.

Per our conversation the Excavation of the VOC impacted Soil will stop, until the Waste hauler and Landfill have been selected.

Therefore please continue your weekly inspections of the plastic tarps and when repairs are made send photographs for proof.

Sent from my iPhone
> On Dec 16, 2019, at 5:27 PM, Matt Kaczmarek <mattkaczmarek@bowyerenvironmental.com> wrote:

> > Hello All, >

> BEC mobilized to the 210/216 Site today at the request of the AQMD to repair wind damage to the tarping plastic covering the excavation and surrounding areas of the site. Please see the attached photos as confirmation that repairs to the plastic sheeting were remedied. Thank you Inspector Haynes for notifying us so that we can avoid potential complaints.

```
notifying us so that we can avoid potential complaints.
> Regards,
> Matt Kaczmarek
> Staff Geologist
> 17011 Beach Boulevard, Suite 900
> Huntington Beach, CA 92647
> Huntington Beach, CA
> Office: (877) 232-4620 Ext. 105
> Cell: (562)754-0162
 ----Original Message----
> From: Castellana, Ben <castellana.ben@epa.gov>
> Sent: Monday, December 16, 2019 3:08 PM
 To: Matt Kaczmarek <mattkaczmarek@bowyerenvironmental.com>; Michal Haynes <mhaynes@aqmd.gov>; Danny
Dolan <dannydolan@bowyerenvironmental.com>
> Subject: RE: Tarps not covering the VOC contaminated Area
> Thank you, Matt; and thank you Michael for your vigilance!
 My current understanding is that site activity will recommence tomorrow; please let me know asap if
that is still the case.
>
 Sincerely,
> Ben Castellana, Ph.D.
 On-Scene Coordinator
> US EPA Region 9
> Superfund Emergency Response
 (562) 305-0694 cell
>
```

> ----Original Message---> From: Matt Kaczmarek <mattkaczmarek@bowyerenvironmental.com>

```
> Sent: Monday, December 16, 2019 2:48 PM
> To: Michal Haynes <mhaynes@aqmd.gov>; Castellana, Ben <castellana.ben@epa.gov>; Danny Dolan
<dannydolan@bowyerenvironmental.com>
> Cc: Jason Aspell <JAspell@aqmd.gov>; Garrett Kakishita <gkakishita@aqmd.gov>; Brett Bowyer
<brettbowyer@bowyerenvironmental.com>
> Subject: RE: Tarps not covering the VOC contaminated Area
> Hi Michal,
> We went by the site on Sunday (12/15) and confirmed that the tarps were where we left them on Thursday
(12/12/19). Today's high winds must have moved them.
> We will mobilize to the site right now and replace the tarps with more sandbags throughout the entire
coverage area.
> Regards,
> Matt Kaczmarek
> Staff Geologist
> 17011 Beach Boulevard, Suite 900
> Huntington Beach, CA 92647
> Huntington Beach, CA 92647
> Office: (877) 232-4620 Ext. 105
> Cell: (562)754-0162
> ----Original Message----
> From: Michal Haynes <mhaynes@aqmd.gov>
> Sent: Monday, December 16, 2019 2:41 PM
> To: Matt Kaczmarek <mattkaczmarek@bowyerenvironmental.com>; castellana.ben@epa.gov; Danny Dolan
<dannydolan@bowyerenvironmental.com>
> Cc: Jason Aspell <JAspell@aqmd.gov>; Garrett Kakishita <gkakishita@aqmd.gov>
> Subject: Tarps not covering the VOC contaminated Area
> Photo taken on 12/16/19
> Area must be secured and recovered, ASAP Faint VOCs at perimeter
> <IMG_1936.JPG>
> <IMG_1932.JPG>
> <IMG_1934.JPG>
```